



UK Manufacturers of Display Equipment & Partition Screens

Established for over 40 years!

01733 394941

sales@rapind.com

www.rapind.com

Universal Display Boards



Scan our QR code to view the product Video



Step 1

Place the round base on the floor and screw the pole into the base using the thread at the end of the pole.



Step 2

Slide a Universal corner moulding down 1 of the 4 channels on the pole.



Step 3

Secure the moulding in place with a screwdriver. Set at the correct height for your display boards. Repeat this process on any remaining poles.



Step 4

Lift the display panel on top of the corner fittings. The corner fittings fit into the frame of the display board.



UK Manufacturers of Display Equipment & Partition Screens

Established for over 40 years!

☎ 01733 394941

✉ sales@rapind.com

💻 www.rapind.com



Step 5

Slide 1 corner moulding down each pole, this will slot into the top corners of the first display board. Twist the pole for easy access to the screw within the corner fixing & secure with a screwdriver.



Step 6

If you're stacking 2 display boards, slide 2 more corner mouldings down the poles, lock into place and add the board on top of the corners.



Step 7

Insert the top corner fixing, twist the pole for access to the screw and secure.



Step 8 (Optional)

To add the header panel, insert the header pole into the top of the main pole. Secure corner mouldings.



Step 9 (Optional)

Add the header panel on top of the corner fixings, finish installation by adding the top corner mouldings and fastening.